

# Oil Field Environmental Incident Summary

**Incident:** 20150207091816      **Date/Time of Notice:** 02/07/2015 09:18  
**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC  
**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC  
**Well Name:** BLMU G-7AH  
**Field Name:** BEAVER LODGE      **Well File #:** 15240  
**Date Incident:** 2/6/2015      **Time Incident:** 09:15      **Facility ID Number:**  
**County:** WILLIAMS      **Twp:** 155      **Rng:** 96      **Sec:** 12      **Qtr:**  
**Location Description:**

**Submitted By:** Jason Henry      **Received By:**  
**Contact Person:** Jason Henry  
3015 16th Street SW, Suite 20  
Minot, ND 58701

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.4 Mile  
**Distance Nearest Water Well:** 0.4 Mile

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site      **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	1	Barrels				
Other						

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 7/10/2015      **Clean Up Concluded:** 2/13/2015

## Risk Evaluation:

The source of the release was secured shortly after the incident occurred.

## Areal Extent:

N/A - the release was contained on the location.

***Potential Environmental Impacts:***

The release occurred above ground and remained on the location. The impacted soil will be excavated and transported off-site for proper disposal.

***Action Taken or Planned:***

The impacted soil will be excavated and transported off-site for proper disposal.

***Wastes Disposal Location:*** At a properly permitted disposal facility.

***Agencies Involved:***

***Updates***

---

***Date:*** 2/9/2015      ***Status:*** Reviewed - Assigned to Other Agency      ***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary, this spill impacted areas on location. NDIC retains oversight.